

Intertek Testing Services NA, Inc. Tel +1-210-635-8100 16015 Shady Falls Road Elmendorf, Texas 78112

Fax +1-210-635-8101 www.intertek.com

Issue Date: July 06, 2023 Letter Report No: G105480517SAT-002L

Recipient's Name: Julia Jun Company Name: Alfrex

Address: 943 Gainesville Hwy. Bldg. 100, Suite 4000 Buford, GA 30518

Phone: 470-589-7449 Email: julia@alfrexusa.com

Subject: Summary Letter for Report No. G105480514SAT-002, for Alfrex regarding testing of Alfrex's 4 mm FR Core ACM Panels to NFPA 285.

Dear Julia Jun,

The assembly described above underwent fire resistance testing to the applicable requirements of NFPA 285, Standard Test Method for Evaluation of Fire Propagation Characteristics of Exterior Non-Load-Bearing Wall Assemblies Containing Combustible Components, 2023 Edition. The test took place on June 29, 2023 and was conducted at the Intertek B&C test facility in Elmendorf, Texas, USA.

Interior cladding - composed of 5/8 in. thick, TYPE X gypsum board. Studs - 2 in. x 6 in., 18 GA galvanized steel studs, 24 in. oc., Exterior sheathing - composed of 5/8 in. DensGlass® Gold Exterior Sheathing (Georgia Pacific). Weather Barrier - one layer of Vapro Shield® Reveal Shield SA Self-Adhered vapor permeable air barrier, installed over the exterior sheathing. Insulation - 3 in. thick Dupont Thermax™ Sheathing (polyiso), used between the vapor barrier and ACM panel, held in place with 5-in. long #12 TEK3 fastener and washers. Supports - 18GA steel zees. Exterior panels - Alfrex 4mm FR Core ACM Panels installed leaving a nominal 1/2 in. gap between panels edges.

The assembly and testing are described in full in Intertek Test Report No. G105480517SAT-002

The conclusion of the report states, "The Alfrex wall system containing 4 mm ACM Panels met the conditions of acceptance outlined in NFPA 285-2023, STANDARD FIRE TEST METHOD FOR EVALUATION OF FIRE PROPAGATION CHARACTERISITCS OF EXTERIOR NON-LOAD-BEARING WALL ASSEMBLIES CONTAINING COMBUSTIBLE COMPONENTS.







SFT-BC-OP-19b

This report is for the exclusive use of Intertek's Client and is provided pursuant to the agreement between Intertek and its Client. Intertek's responsibility and liability are limited to the terms and conditions of the agreement. Intertek assumes no liability to any party, other than to the Client in accordance with the agreement, for any loss, expense or damage occasioned by the use of this report. Only the Client is authorized to permit copying or distribution of this report and then only in its entirety. Any use of the Intertek name or one of its marks for the sale or advertisement of the tested material, product or service must first be approved in writing by Intertek. The observations and test results in this report are relevant only the sample tested. This report by itself does not imply that the material, product or service is or has ever been under an Intertek certification program.

Version: 02 August 2017 Page 1 of 2



If you have any questions regarding this letter report, please do not hesitate to contact the undersigned: Sincerely,

INTERTEK TESTING SERVICES NA, INC.

Completed by:	Abel de Hoyos	Reviewed by:	Mike Dey
	Senior Project Manager -		
Title:	Fire Resistance	Title:	Senior Project Engineer
Signature:		Signature:	With Deg
Date:	07/06/2023	Date:	07/06/2023



